



Vehicle History Report™

US \$44.99

1989 SAAB 900 TURBO

VIN: YS3AT76L1K7021013
CONVERTIBLE
2.0L I4 F
GASOLINE
FRONT WHEEL DRIVE



Damage reported >



9 Service history records >



37 Detailed records available >



128,832 Last reported odometer reading >



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 5/27/25 at 11:04:12 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

05/22/2025

Damage reported

- Vehicle damaged in multiple places



Additional History

Not all accidents / issues are reported to CARFAX

Summary

Total Loss ⓘ

No total loss reported to CARFAX.



Structural Damage ⓘ

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.



Airbag Deployment ⓘ

No airbag deployment reported to CARFAX.



Odometer Check ⓘ

No indication of an odometer rollback.



Accident / Damage ⓘ

Damage reported: 05/22/2025.

[Damage Reported](#)

Manufacturer Recall ⓘ

No open recalls reported to CARFAX.

No Recalls Reported

Basic Warranty ⓘ

No data reported to CARFAX.










No Data Reported









Title History

Summary



CARFAX Title History		Summary
Damage Brands ⓘ Salvage Junk Rebuilt Fire Flood Hail Lemon		No Problem
Odometer Brands ⓘ Not Actual Mileage Exceeds Mechanical Limits		No Problem

CARFAX Detailed History				Glossary
Date	Mileage	Source	Comments	
01/17/1995	52,265	New York Motor Vehicle Dept. Elmsford, NY	Title issued or updated	
09/15/1998	90,052	New York Inspection Station New York City Area	Passed safety inspection - Passed emissions inspection	
01/13/2000	100,078	New York Inspection Station New York City Area	Passed safety inspection - Failed emissions inspection - Passed emissions inspection	
07/14/2000 		Palisades Volvo Mazda West Nyack, NY 845-358-2900 palisadesvolvo.com	Vehicle serviced - A/C system checked - Battery/charging system checked - Glass checked	
08/02/2000 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwrmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Cooling system checked	
10/30/2000 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwrmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Battery/charging system checked - Window(s) checked	
06/04/2001 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwrmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Window(s) checked	
01/15/2002 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwrmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Battery replaced - Exhaust system checked - Interior lights checked - Radio/sound system checked	
06/01/2002	107,760	New York Inspection Station New York City Area	Passed safety inspection - Passed emissions inspection	
04/30/2003		New York Motor Vehicle Dept. Elmsford, NY	Title issued or updated	
09/09/2004	108,586	New York Inspection Station	Passed safety inspection - Passed emissions inspection	

09/09/2004	100,000	New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/06/2004		New York Motor Vehicle Dept. Ossining, NY	Title issued or updated
10/07/2004 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Maintenance inspection completed - A/C system checked - Engine oil/fluid leak checked - Emissions inspection performed - Safety inspection performed
10/15/2004	108,873	New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/21/2004 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced - Engine checked
11/10/2004		New York Motor Vehicle Dept. Ossining, NY	Title issued or updated
09/09/2005 		BMW Mt. Kisco Mount Kisco, NY 914-241-4444 bmwmtkisco.com ★ 4.9 / 5.0 23 Verified Reviews 	Vehicle serviced
10/04/2005	112,649	New York Inspection Station	Passed safety inspection - Passed emissions inspection
04/18/2008		New York Motor Vehicle Dept. Ossining, NY	Title issued or updated
05/13/2008	112,685	New York Inspection Station	Passed safety inspection - Passed emissions inspection
05/14/2009	113,402	New York Inspection Station	Passed safety inspection - Passed emissions inspection
03/24/2010		New York Motor Vehicle Dept. Ossining, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
08/13/2010	113,424	New York Inspection Station	Passed safety inspection - Passed emissions inspection
04/02/2014		New York Motor Vehicle Dept. Ossining, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
05/29/2014	113,684	New York Inspection Station	Passed safety inspection - Emissions inspection performed
02/21/2016		New York Motor Vehicle Dept. Ossining, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection

Ussining, NY

- Passed safety inspection

04/25/2016	114,547	New York Inspection Station	Passed safety inspection - Emissions inspection performed
08/21/2018		New York Motor Vehicle Dept. Amawalk, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/23/2018	115,330	New York Inspection Station	Passed safety inspection - Emissions inspection performed
09/04/2018		New York Motor Vehicle Dept. Amawalk, NY	Title issued or updated - New owner reported
09/09/2019	123,342	New York Inspection Station	Passed safety inspection - Emissions inspection performed
01/24/2020 	123,594	AAMCO Transmissions Mahopac, NY 845-628-9222 aamco.com ★ 4.8 / 5.0 9 Verified Reviews ✓	Vehicle serviced - Automatic transmission replaced - Oil and filter changed
01/29/2020		New York Motor Vehicle Dept. Amawalk, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/28/2021	124,760	New York Inspection Station	Passed safety inspection - Emissions inspection performed
02/03/2022		New York Motor Vehicle Dept. Amawalk, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
11/17/2023	128,832	New York Inspection Station	Passed safety inspection - Emissions inspection performed
05/22/2025 		Damage Report	Damage reported - Vehicle damaged in multiple places



Not all damage is caused by an accident. Get the car inspected before you buy. [Learn More](#)

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

[Full Glossary](#)

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/27/25 at 11:04:12 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

Inspections

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.
5/27/25 11:04:12 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1989 SAAB 900 vehicle (VIN: YS3AT76L1K7021013), which is based on information supplied to CARFAX and available as of 5/27/25 at 12:04 PM (EDT).

Customer Signature

Date

Dealer Signature

Date